



FOR LEFT LANE CLOSURE ON BRIDGE:
 1. REMOVE W1-4L AND W13-1 SIGNS,
 2. REMOVE 125' MERGE TAPER,
 3. SHIFT DRUMS FROM RIGHT LANE TO LEFT LANE WITH SAME SPACING.

| | |
|------------------|---------------|
| MESSAGE NO. 1 | MESSAGE NO. 2 |
| LEFT LANE CLOSED | MERGE RIGHT |

11/3/2023
 U:\Traffic\Transportation Management\Plan\TCP\PLAN SHEETS\15BPR.102.3_TMP_08_WESTBOUND_LANE_CLOSURE_DETAIL.dgn
 angood

| | | | |
|---|--|--|--|
| <p>Stantec Consulting Services Inc. 801 Jones Franklin Road Suite 300 Raleigh, NC 27606 Tel. 919.851.6866 Fax. 919.851.7024 www.stantec.com License No. F-0672</p> | <p>DocuSigned by </p> <p>11/3/2023</p> <p>DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED</p> | | <p style="text-align: center;">WESTBOUND LANE CLOSURE DETAIL</p> |
|---|--|--|--|