

SUBSTRUCTURE REPAIR QUANTITY TABLE QUANTITIES REPAIRS - END BENT 1 & 2 ACTUAL **ESTIMATE** AREA AREA VOLUME VOLUME SHOTCRETE REPAIRS SF 0 0 0.5 1.0 AREA SF VOLUME AREA SF VOLUME CONCRETE REPAIRS CF 0 0 0 LINEAR LINEAR **EPOXY RESIN INJECTION** FT 0 0

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1" BEHIND REBAR AND MIN. 2" CLEAR TO SAWCUT. SEE REPAIR DETAILS.

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE REPAIR QUANTITY TABLE.

CONCRETE REPAIRS MAYBE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

PROJECT NO. HI-0017

ROBESON COUNTY

BRIDGE NO. 770447



STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION
RALEIGH

SUBSTRUCTURE END BENT 1 & END BENT 2

REVISIONS SHEET NO DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2 A SHEET NO. BY: DATE: SIGNATURES COMPLETED 6