

SUMMARY OF QUANTITIES FOR SPAN C AND APPROACH SLAB 2

	ESTIMATE	ACTUAL
SCARIFYING BRIDGE DECK	228.4 SY	
SHOTBLASTING BRIDGE DECK	228.4 SY	
CLASS II SURFACE PREPARATION	4.4 SY	
CLASS III SURFACE PREPARATION	0.0 SY	
CONCRETE DECK REPAIR FOR PC OVERLAY	4.4 SY	
POLYESTER POLYMER CONCRETE MATERIALS	7.9 CY	
EPOXY POLYMER CONCRETE MATERIALS (ALTERNATE)	7.9 CY	
PLACING & FINISHING PC OVERLAY	228.4 SY	
GROOVING BRIDGE DECK	1,893.2 SF	

QUANTITIES FOR PC OVERLAY ARE BASED ON OVERLAY DEPTH PLUS AN ADDITIONAL 1/4" TO ACCOUNT FOR IRREGULARITIES IN SCARIFICATION PROCESSES.

NOTES:

DECK SURFACE REPAIR QUANTITIES REPRESENT ESTIMATED VALUES OF CLASS II SURFACE PREPARATION AND CONCRETE DECK REPAIR AFTER REMOVAL OF UNSOUND CONCRETE. (MIN. 2" CLEAR TO SAWCUT). SEE CONCRETE DECK REPAIR FOR PC OVERLAY SPECIAL PROVISION.

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE ACTUAL REPAIR QUANTITY TABLE.

FOR CONCRETE DECK REPAIR FOR PC OVERLAY, SEE SPECIAL PROVISIONS.

FOR SECTION A-A AND B-B, SEE JOINT DETAILS SHEET.

REPAIR LEGEND

SHOTBLASTING AND SCARIFICATION OF OF BRIDGE DECK FOR PC OVERLAY

APPROX. AREA CLASS II SURFACE PREPARATION

PROJECT NO. HI-0015

COLUMBUS

COUNTY

SHEET NO.

S2-5

TOTAL SHEETS 18

230086 BRIDGE NO. ___

SHEET 3 OF 3

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

SURFACE PREPARATION SPAN C

REVISIONS NO. BY: DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

11/21/2023 S:\DPG1\Division6\HI-0015\230086\PLANS\402_009_HI0015_SMU_DSR_C_S2-5_230086.dgn aabraha

G. AYES

CHECKED BY : ___

DESIGN ENGINEER OF RECORD: