

North Carolina  
Department of Environment and Natural Resources

Division of Waste Management

Beverly Eaves Perdue, Governor  
Dee Freeman, Secretary  
Dexter R. Matthews, Director

 FILE COPY



## UNDERGROUND STORAGE TANK SECTION

July 2, 2009

Mr & Ms. William and Juanita Register  
1707 US Highway 17 North  
New Bern, NC 28560

**RE: Notice of No Further Action 15A NCAC 21.0407(d)  
Risk Based Assessment and Corrective Action for  
Petroleum Underground Storage Tanks  
Former Esso/Exxon (Register Property)  
1709 US Highway 17 North  
Bridgeton, Craven County, North Carolina  
Incident Number: 31413  
Risk Classification: Low**

Dear Mr & Ms. Register:

Underground Storage Tank (UST) Section of the Division of Waste Management, Raleigh Central Office received a Site Assessment Report for the above referenced site. A Review of the report indicates that soil contamination does not exceed of the soil-to-groundwater maximum soil contaminant concentrations (MSCC), established in Title 15A NCAC 2L.0411 and that groundwater contamination does not exceed the groundwater quality standards established in Title 15A NCAC 2L .0202.

Based on information provided to date, the UST Section finds it appropriate to classify risk of the discharge or release as Low. Furthermore, the UST Section determines that no further action is warranted for this incident. This determination shall apply unless the UST Section later finds that the discharge or release poses an unacceptable risk or a potentially risk to human health or the environment or additional information is provided to warrant re-assessment of the site.

Division of Waste Management / UST Section  
1637 Mail Service Center, Raleigh, North Carolina 27699 637  
Phone: 919-733-8486 \ Fax: 919-733-9413  
Internet: <http://www.wastenotnc.org/>

Pursuant to 15A NCAC 2L .0407(a) you have a continuing obligation to notify the UST section of any changes that you know of or should of, that might affect the level of the risk assigned to the discharge or release. Please be advised that all monitoring or injection wells used to investigate or remediate this incident were abandoned properly in accordance with 15A NCAC 2C .0113 and 0.114, respectively by the State Lead contractor.

If you have any questions concerning this notice, please contact Hassan Osman at (919) 715-6177.

Sincerely

  
George C. Matthis, Jr.  
Trust Fund Branch Head

cc: WaRO-FYI  
FTF-File