
STATE OF NORTH CAROLINA
DIVISION OF HIGHWAYS



UNION COUNTY

LOCATION: BRIDGE 258 ON SR 1008 OVER SOUTH FORK
CROOKED CREEK AND IMPROVEMENTOF THE
INTERSECTION OF SR 1009 AND SR 1371
TYPE OF WORK: TRAFFIC SIGNAL AND SCHOOL FLASHER (RELOCATION)





Refer to "Roadway Standard Drawings NCDOT" dated January 2012 and "Standard Specifications for Roads and Structures" dated January 2012.

Index of Plans

Indian Trail

 Sheet #
 Reference #

 Sig. 1.0

 Sig. 2.0 - 2.2
 10-2176

 Sig. 3.0 - 3.3
 10-0611

Sig. 4.0

Vicinity

Fincher Rd

DETOUR ----

1008/\$

VICINITY MAP

PROJECT

Location/Description

Title Sheet

SR 1009 (Old Monroe Road) at SR 1371 (Southfork Road) / Garmon Drive

SR 1009 (Old Monroe Road) at SR 1008 (Waxhaw – Indian trail Road)

Relocate School Signs & Beacons

INTELLIGENT TRANSPORTATION AND SIGNALS UNIT

Contacts:

Timothy J. Williams, PE - Western Region Signals Engineer George C. Brown, PE - Signal Equipment Design Engineer Prepared in the Office of:

DIVISION OF HIGHWAYS

TRANSPORTATION MOBILITY AND SAFETY

DIVISION

Mobility and Safety

Repared in the Office of:

DIVISION SAFETY

and Signals

750 N Greenfield Parkway Garner NG 2

750 N. Greenfield Parkway, Garner, NC 27529