* TOTAL BILL OF MATERIAL													
BRIDGE	MOBILIZATION	INCIDENTAL MILLING	ASPHALT CONCRETE SURFACE COURSE, TYPE S9.5B	ASPHALT BINDER FOR PLANT MIX	Δ REINFORCING STEEL	SHOTCRETE REPAIRS	EPOXY RESIN INJECTION	BRIDGE JOINT REMOVAL	PILE JACKETS	REJACKETS	SILICONE JOINT SEALANT	CONCRETE DECK REPAIR FOR EPOXY OVERLAY	EPOXY OVERLAY SYSTEM- MECHANICALLY DISTRIBUTED
	LUMP SUM	SO.YDS.	TONS	TONS	LBS.	CU.FT.	LIN.FT.	LIN.FT.	LIN.FT.	LIN.FT.	LIN.FT.	SO.FT.	SQ.FT.
TYRRELL #7	LUMP SUM	267	22.5	1.5	10	1,363.5	98.1	9,429	7,013.5	438	9,489	473	387,507

* EXCLUDES BILL OF MATERIAL FOR PIVOT PIER PILE REPAIRS AND FOR MECHANICAL AND ELECTRICAL PLANS, SEE SHT'S SA-1 THRU SA-3 AND SHT'S G-1 THRU M-23.

A REINFORCING STEEL QUANTITY IS NOT ANTICIPATED, A TOKEN PAY ITEM IS INDICATED FOR PRICING PURPOSES, IN CASE UNANTICIPATED REPAIRS ARE ENCOUNTERED.

Docusigned by:

Robbie Weise/10/2016

CEA153463B6D43D...

PROJECT NO. B-5936

TYRRELL COUNTY
BRIDGE NO. 7

STATE OF NORTH CAROLINA
DEPARTMENT OF TRANSPORTATION
RALEIGH

TOTAL BILL OF MATERIAL

> SHEET NO. S-1

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED REVISIONS

REVISIONS

DATE: NO. BY: DA

 DRAWN BY:
 S. T. SANDOR
 DATE : . 06/2016

 CHECKED BY:
 R. N. WEISZ
 DATE : . 06/2016