


DocuSign Envelope ID: 3CB4EFFD-4CB3-42A7-B538-171F939806D9






SIDE VIEW NORTH FACE





SIDE VIEW

SOUTH FACE



+



PROPOSED REPAIR AREAS

SUBSTRUCTURE SPALL/DELAMINATION

 DRAWN BY :
 J.H.DUKE
 DATE :
 07-16

 CHECKED BY :
 S.L.CULLUM
 DATE :
 07-16

 DESIGN ENGINEER OF RECORD:
 S.L.CULLUM
 DATE :
 07-16
DATE : 07-16 DATE : 07-16

	PROJECT NO. <u>B-5937</u> <u>CURRITUCK/DARE</u> COUNTY STATION: <u>BRIDGE NO. 16</u>					
19697095C75A467 TH CARO	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEICH					
12/13/2016	SUBSTRUCTURE CONC. REPAIR - BENT 38					
12/13/2010	REVISIONS SHEET NO.					
OCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO.	ВΥ:	DATE:	S-57
FINAL UNLESS ALL SIGNATURES COMPLETED	1 2		3 4			TOTAL SHEETS

1

Б

