

DocuSign Envelope ID: C2D4D89C-FD79-477E-9989-B7156183A4B2






ELEVATION WEST FACE



SIDE VIEW

NORTH FACE



SIDE VIEW SOUTH FACE


ELEVATION EAST FACE

+




PROPOSED REPAIR AREAS

SUBSTRUCTURE SPALL/DELAMINATION




SUBSTRUCTURE CONC. REPAIR - BENT 101 SUBSTRUCTURE CONC. REPAIR - BENT 101 REVISIONS SHEET NO. S-120 FINAL UNLESS ALL STREFT SHEET NO. S-120 SHEET NO. SHEET NO. S-120 SHEET NO. SHEET NO. S-120 SHEET NO. SHEET NO. S-120 SHEET NO. SHEET NO. S-120 SHEET NO. SHEET NO. SHEET NO. SHEET NO. SHEET NO. S-120 SHEET NO. SHEET S	Sanuel Cullun 19097096675A467 19087 H CAROLANA 1908 FESSION		DEPA		0			TION
DOCUMENT NOT CONSIDERED FINAL UNLESS ALL 10 3 51EET NO. 1074L SHEETS	SEAL 043571	SUBSTRUCTURE CONC. REPAIR - BENT 101						
FINAL UNLESS ALL 1 3	12/13/2016	REVISIONS SHEET NO.						
FINAL UNLESS ALL 1 SHEETS	ACUMENT NOT CONSTREPED	NO.	BY:	DATE:	NO.	BY:	DATE:	S-120
SIGNATURES COMPLETED 2 4		1			3			TOTAL SHEETS
	SIGNATURES COMPLETED	2			4			

PROJECT NO.



-DocuSigned by:

ſn



B-5937

CURRITUCK/DARE COUNTY STATION: BRIDGE NO. 16