


DocuSign Envelope ID: 380B8827-4546-4BD1-B9EE-A4586C518FB5





ELEVATION WEST FACE





SIDE VIEW SOUTH FACE

ELEVATION EAST FACE


+

+



PROPOSED REPAIR AREAS


SUBSTRUCTURE SPALL/DELAMINATION



TSA467 AROUTING TRANSPORTATION STOPPARTMENT OF TRANSPORTATION RALEICH SUBSTRUCTURE CONC. REPAIR - BENT 137 SHEET NO. SHEET NO.						
						SHEET NO.
NO.	BY:	DATE:	NO.	BY:	DATE:	S-156
1			3			TOTAL SHEETS
2			4			
	1	NO. BY:	DEPARTMENT SUBSTF REPAI	DEPARTMENT OF SUBSTRUC REPAIR REVISION NO. BY: DATE: NO. 1	DEPARTMENT OF TRAI RALEIGH SUBSTRUCTURI REPAIR - BE REVISIONS NO. BY: DATE: NO. BY: 1 3	DEPARTMENT OF TRANSPORTA RALEIGH SUBSTRUCTURE CONC REPAIR - BENT 137 REVISIONS REVISIONS NO. BY: DATE: NO. BY: DATE: 1 3

PROJECT NO.___

DocuSigned by: Sanuel Cullum



B-5937

CURRITUCK/DARE COUNTY STATION: BRIDGE NO. 16