

DRAWN BY :

CHECKED BY : _

S. Wance

J. YANNACCONE

+

+

29-JAN-2017 17:28 R:\Structures\FinalDrawings\590159\I-5894_590159_SMU_SPANS_A-K.dgn

DATE : 12/2016

DATE : 1/2017

AS-BUILT REPAIR QUANTITY TABLE

TOP OF DECK REPAIRS

SPAN I					
	ESTIMATE	ACTUAL			
SCARIFYING BRIDGE DECK	2,268 SY				
CLASS II SURFACE PREPARTION	0.0 SY				
CONCRETE DECK REPAIR FOR PPC OVERLAY	0.0 SY				
SHOTBLASTING BRIDGE DECK	2,268 SY				
PPC MATERIALS	79.2 CY				
PLACING AND FINISHING PPC OVERLAY	2,268 SY				
GROOVING BRIDGE FLOORS	19,547 SF				
BRIDGE JOINT DEMOLITION	72.5 SF				

OUANTITIES IN TABLES REPRESENT ESTIMATED VALUES OF CLASS II SURFACE PREPARATION AND CONCRETE DECK REPAIR FOR PPC OVERLAY AFTER REMOVAL OF UNSOUND CONCRETE (MIN. 2" CLEAR TO SAW CUT). SEE OVERLAY SURFACE PREPARATION FOR POLYESTER POLYMER CONCRETE SPECIAL PROVISION.



APPROX. CLASS II AREA BRIDGE JOINT DEMOLITION TEST LOCATION

	PROJEC	GAST	ON	-5894 CO 59	1 UNTY	
SHEET 6 OF 7						
DocuSigned by: John Hammallone DEPARTMENT OF TRANSPORTATION						
- 7BC36E0EEEEEE	PLAN OF SPAN SPAN I					
PACKER CONT						
5/2017						
	REVISIONS SHEET N					
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY:	DATE:	S-23	
FINAL UNLESS ALL SIGNATURES COMPLETED	1 2		3 4		TOTAL SHEETS 27	