





-	EPOXY	COATING
---	-------	---------

- SHOTCRETE REPAIR

ERI - EPOXY RESIN INJECTION

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN

REPAIR QU	JANTI	ΤΥ ΤΑ	BLE	
DEDATOS DENT 16	QUANTITIES			
REPAIRS BENT 16	ESTIMATE		ACTUAL	
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL, CORNER)	0.0	0.0		
COLUMN	0.0	0.0		
STRUT	0.0	0.0		
FOOTING	0.0	0.0		
EPOXY COATING	AREA SF	AREA SF		
FTG (VERTICAL FACE)	0.0			
FTG (HORIZONTAL, CORNER)	334.4			
EPOXY RESIN INJECTI	LN.FT	LN	.FT	
САР	0.0			
COLUMN	0.0			
STRUT	0.0			
FOOTING	0.0			

REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.