



AS-BUILT REPAIR QUANTITY TABLE

	BENT 1 REPAIRS	QUANTITIES						
		ESTI	MATE	ACTUAL				
	SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	DEPTH FT	VOLUME CF		
	CAP (VERTICAL FACE)	164.4	82.2					
	CAP (HORIZONTAL, CORNER)	15.0	7.5					
	COLUMN	0	0					

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPÁIR DETAILS.

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE, IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN REPAIR DETAILS" SHEET.

- SHOTCRETE REPAIR

- CONCRETE REPAIR

PROJECT NO. I-5889A BUNCOMBE _ COUNTY 344 BRIDGE NO._



STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> BENT 1 SPAN A SIDE

	REVISIONS							
NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	DATE:	S-2	
UNLESS ALL	1			3			TOTA SHEE	
RES COMPLETED	2			4			20	

__ DATE : <u>9/2017</u> __ DATE : <u>10/2017</u> D.PETRY R.F. WERTMAN

DRAWN BY : __

PLANS PREPARED BY:

2610 Wycliff Road
Suite 102
Raleigh NC 27607-3073
(919) 420-7660
FINAL U'
SIGNATURE