

## NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN REPAIR DETAILS"SHEET.

- SHOTCRETE REPAIR

- CONCRETE REPAIR

PROJECT NO. <u>I-5889A</u> <u>BUNCOMBE</u> county Bridge no. <u>347</u>						
	TH CAROLINE	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH				
	BENT 1 SEAL 020208 BENT 1 SPAN B SIDE					
	Ein Bhuh fr 11/16/2017 BA9F91762D7044A					
		REVISIONS				SHEET NO.
	DOCUMENT NOT CONSIDERED	NO. ВҮ:	DATE:	NO. BY:	DATE:	S-43 TOTAL SHEETS
2	FINAL UNLESS ALL SIGNATURES COMPLETED	2		<b>③</b> 4		SHEETS 208