

CHECKED BY :



AS-BUILT REPA	IR QL	JANTI	ΓΥ -	TABI	LE	
END BENT 1	QUANTITIES					
	ESTIMATE		ACTUAL			
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	DEPTH FT	VOLUME CF	
CAP (VERTICAL FACE)	0	0				
CAP (HORIZONTAL, CORNER)	0	0				
END BENT 2	QUANTITIES					
		ESTIMATE		ACTUAL		
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	DEPTH FT	VOLUME CF	
CAP (VERTICAL FACE)	0	0				
CAP (HORIZONTAL, CORNER)	0	0				
VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2" CL TO SAWCUT. SEE REPAIR DETAILS. NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE. SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER. FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS. FOR CONCRETE REPAIR, SEE SPECIAL PROVISIONS. FOR CONCRETE REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN REPAIR DETAILS" SHEET.						

-	PROJECT NO. <u>I-5889A</u> <u>BUNCOMBE</u> county BRIDGE NO. <u>369</u>
NRTH CAROL	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH
SEAL O20208	END BENTS 1 & 2
Ein Bhil fr 11/16/2017 BASF91762D7044A	
ad	REVISIONS SHEET NO.
DOCUMENT NOT CONSIDERED	NO. BY: DATE: NO. BY: DATE: S-141
FINAL UNLESS ALL SIGNATURES COMPLETED	1 3 TOTAL SHEETS 2 4 208