

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN REPAIR DETAILS"SHEET.

- SHOTCRETE REPAIR

- CONCRETE REPAIR

	PROJECT NO. <u>I-5889A</u> <u>BUNCOMBE</u> county BRIDGE NO. <u>369</u>				
RTH CAROL OFESSION SEAL 020208	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH				
DocuSigned by:	BENT 1 Span B Face				
BA9F91762D7044A	REVISIONS SHEET NO.				
	NO. BY:	i	NO. BY:	DATE:	S-143
 DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 	1		3 4		total sheets 208