

²⁹⁻MAY-2019 11:57 R:\Structures\FinalPlans\401_019_15BPR40_SMU_SBR_B1A_S1-10_100481.dgn amlee

+

+

AS-BUILT REPA	IR QL	JANTI	ΤΥ ΤΑ	BLE
BENT 1 SPAN A FACE	QUANTITIES			
DENT I STAN A TACE	ESTIMATE		ACTUAL	
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.
САР	14.7	7.4		
COLUMN	0.0	0.0		
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.
САР	0.0	0.0		
COLUMN	0.0	0.0		
EPOXY RESIN INJECTION		LIN.FT.	LIN.FT.	
САР		0.0		
COLUMN		0.0		
EPOXY COATING		SQ.FT.	SQ.FT.	
TOP OF BENT CAP		209.9		

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR

CLEAN AND REMOVE DEBRIS FROM THE TOP OF THE CAP AND APPLY EPOXY PROTECTIVE COATING. EPOXY COATING SHALL BE APPLIED TO THE TOP SURFACE OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY PLATES. FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAYBE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

SHOTCRETE REPAIR AREA

CONCRETE REPAIR AREA

ERI - EPOXY RESIN INJECTION

PROJECT NO	15B	PR.40
BUNCOM	1BE	
BRIDGE NO	100	481

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

B04B5A4F2FAD484					
5/29/2019		SHEET NO.			
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY:	DATE:	S1-10
FINAL UNLESS ALL	1		3		TOTAL SHEETS
SIGNATURES COMPLETED	2		4)		18