STEEL REPAIRS WELD REPAIR: LUMP SUM LUMP SUM W3 LUMP SUM W4 LUMP SUM HOLE REPAIR: 12 EA. TYPE I 3 EA. TYPE II 1 EA. TYPE III PACK RUST REPAIR: 17 EA. TYPE I 6 EA. TYPE II CLEANING AND PAINTING OF EXISITNG 6,775 SY WEATHERING STEEL LUMP SUM POLLUTION CONTROL PAINTING LUMP SUM CONTAINMENT GUSSET PLATE LUMP SUM RETROFIT

BILL OF MATERIAL

NOTES:

FOR CLEANING AND PAINTING EXISTING WEATHERING STEEL, SEE SPECIAL PROVISIONS.

CLEAN AND PAINT GIRDERS 1 & 4 BEARINGS AT PIERS 2 & 3.

CONTRACTOR SHALL REMOVE ALL VEGETATION AND FILTH FROM THE STRUCTURE

> PROJECT NO. HENDERSON

15BPR.20

COUNTY

35+30.22 -L-

SHEET 14 OF 14

AECOM AECOM TECHNICAL SERVICES OF NC, INC. 701 CORPORATE CENTER DRIVE, SUITE 475 RALEIGH, NC 27607 (919) 854-6200 www.aecom.com AECOM License No. F-0342

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

REHABILITATION

STRUCTURAL STEEL REPAIRS

SHEET NO REVISIONS NO. BY: S-94 DATE: DATE: BY: TOTAL SHEETS

FULL LENGTH--FULL LENGTH

> PAINTING LIMITS OF GIRDERS 1 & 4 FULL LENGTH

GIRDER 4

CLEANING AND PAINTING OF EXISTING WEATHERING STEEL SUPERSTUCTURE

DATE : 2/2019 DATE : 2/2019 DATE : 2/2019 DATE : 2/2019 DRAWN BY : M. TOM CHECKED BY : G. COLS DESIGNED BY : J. SLOAN

DESIGN CHECKED BY : E. ZHOU

GIRDER 1

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED