


PLAN OF SPANS

(TOPSIDE)

FOR CLARITY, THREE BAR METAL RAILS ARE NOT SHOWN.
FOR CLARITY, THE PEDESTRIAN SAFETY RAIL IS NOT SHOWN.



PLAN OF SPANS

(TOPSIDE)

FOR CLARITY, THREE BAR METAL RAILS ARE NOT SHOWN.

FOR CLARITY, THE PEDESTRIAN SAFETY RAIL IS NOT SHOWN.

WSP USA Inc.
434 FAYETTEVILLE STREET
SUITE 1500
RALEIGH, NC 27601
TEL: 1.919.836.4040
LICENSE NO. F-0165

	REPAIR QUANTITY TABLE		
	EPOXY OVERLAY SYSTEM	QUANTITIES	
		ESTIMATE	ACTUAL
		AREA SF	AREA SF
	APPROACH SLAB AT END BENT 1		
	JOINT REPAIR	QUANTITIES	
		ESTIMATE	ACTUAL
		LENGTH LN.FT.	LENGTH LN. FT.
	FOAM JOINT SEAL		
	POURABLE SILICONE JOINT SEALANT		

NOTES

REFER TO SPECIAL PROVISIONS.

LEGEND

FOR EPOXY OVERLAY REPAIR

PROJECT NO. 15BPR.19
NEW HANOVER COUNTY

BRIDGE NO. 640021

SHEET 2 OF 3

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

10/19/2020

DEPARTMENT OF TRANSPORTATION
RALEIGH

SUPERSTRUCTURE
PLAN OF SPANS

REPAIRS
PARTIAL SPAN 7 THRU
PARTIAL SPAN 13

REVISIONS

BY: DATE: NO. BY: DATE: S-7

3 TOTAL SHEETS
58

10/18/2020

DRAWN BY: M.J. OSTRISHKO DATE : JUL 2018
CHECKED BY: C.J. HOWARD DATE : JUL 2018