NOTES: REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANITITY TABLE. PAYMENT FOR CLASS II SURFACE PREPARATION IS BASED UPON SQUARE YARDS OF ADDITIONAL DEMOLITION REQUIRED FOLLOWING SCARIFICATION OF BRIDGE DECK. SEE "OVERLAY SURFACE PREPARATION" SPECIAL PROVISION. SPAN D © BENT 4 —

SUMMARY OF QUANTITIES FOR SPAN "E"

ESTIMATE ACTUAL

SCARIFYING BRIDGE DECK 420.3 SY

CLASS II SURFACE PREPARATION - SY

CONCRETE DECK REPAIR FOR PC OVERLAY - SY

SHOTBLASTING BRIDGE DECK 420.3 SY

PC MATERIALS 14.6 CY

PLACING AND FINISHING PC OVERLAY 420.3 SY

3422 SF

SPAN F

GROOVING BRIDGE FLOORS

\$ 150 of Class

PLAN OF SPAN "E"

120'-1"(SPAN E)

] - SCARIFYING OF BRIDGE DECK

_ APPROX.AREA CLASS II SURFACE PREPARATION

PLANS PREPARED BY:

Suite 900
Raleigh, NC 27603
(919) 420-7660
Excellence Delivered As Promised

NC Lic. No. F-0270

SEAL
020208

SEAL
020208

NGINEER

Docusigned by:

MINIMAL D. 9/2/2021

ACB8082119D74CD...

SURFACE PREPARATION SPAN "E"

PROJECT NO. B-4626

AND DAVIDSON COUNTY

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

790008

STANLY, ROWAN

BRIDGE NO._

OCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2

REVISIONS

BY: DATE: NO. BY: DATE:

3 TOTAL SHEETS
125

 DRAWN BY :
 M. LEE
 DATE :
 3/2021

 CHECKED BY :
 R. NELSON
 DATE :
 4/2021

+