

+

+

AS-BUILT REPAIR QU	JANTITY	TABLE
TOP OF DECK REPAIRS		
	ESTIMATE	ACTUAL
SCARIFYING BRIDGE DECK	754 SQ.YDS.	
CLASS II SURFACE PREPARATION	2.0 SQ. YDS.	
CONCRETE DECK REPAIR FOR PC OVERLAY	2.0 SQ. YDS.	
SHOTBLASTING BRIDGE DECK	754 SQ.YDS.	
PC MATERIALS	36.7 CU.YDS.	
PLACING AND FINISHING PC OVERLAY	754 SQ.YDS.	
GROOVING BRIDGE FLOORS	6360 SQ.FT.	

TOP OF DECK REPAIR QUANTITIES REPRESENT ESTIMATED VALUES OF CLASS II SURFACE PREPARATION AND CONCRETE DECK REPAIR FOR PPC OVERLAY AFTER REMOVAL OF UNSOUND CONCRETE.(MIN.2″CLEAR TO SAWCUT).SEE OVERLAY SURFACE PREPARATION FOR POLYESTER POLYMER CONCRETE SPECIAL PROVISION.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE. FOR SECTION B-B, SEE "JOINT DETAILS" SHEET.

APPROX.CLASS II SURFACE PREPARATION

	PROJ.NO. <u>I-5746C</u> <u>MECKLENBURG</u> COUNTY BRIDGE NO. <u>590322</u>	
DocuSigned by:	SHEET 3 OF 3	
DZEE938FAB674C5	DEPARTMENT OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH DECK SURFACE REPAIR SPAN C	
	SI AN C	
8/23/2021		
	REVISIONS SHEET NO.	
DOCUMENT NOT CONSIDERED	NO. BY: DATE: NO. BY: DATE: S5-6	
FINAL UNLESS ALL	1 SHEETS	
SIGNATURES COMPLETED	2 4 274	