

<u>PLAN</u>

NOTES

FOR BEAM REPAIR DETAILS, SEE "BEAM SECTION REPAIR DETAILS" SHEET.

FOR BEAM PLATING DETAILS, SEE "BEAM PLATING REPAIR DETAILS" SHEET.

FOR BRIDGE JACKING DETAILS, SEE "JACKING DETAILS" SHEET.

THE LOCATIONS AND DIMENSIONS OF THE AREAS FOR REPAIR ARE BASED ON THE BEST INFORMATION AVAILABLE. THE CONTRACTOR, IN CONJUNCTION WITH THE ENGINEER, SHALL VERIFY THE LOCATION AND EXTENT OF REPAIR AREAS PRIOR TO STEEL FABRICATION. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

FOR UNDERSIDE OF DECK AND DIAPHRAGM REPAIRS, SEE "OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR" SHEET.

UNDERSIDE REPAIR

EPOXY RESIN INJECTION (ERI)

- 1 BEAM NUMBER
- B) BEAM END REPAIR
- P PLATING REPAIR
- S STIFFENER REPAIR
- D BIBEHRAGAPHREAROMIRREPAIR

DRAWN BY :	R.L.PUTEK/E. BAYISSA	DATE : <u>07/2021</u>
CHECKED BY : _	H.A. LOCKLEAR	DATE : <u>07/2021</u>

AS-BUILT REPAIF	R QUA	NTIT	Y TA	BLE	
UNDERSIDE OF DECK REPAIRS					
	ESTIMATE		ACTUAL		
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.	
UNDERSIDE OF DECK	0.0	0.0			
UNDERSIDE OF OVERHANG	6.2	2.1			
INTERIOR DIAPHRAGMS	0.0	0.0			
	ESTIMATE		ACTUAL		
UNDERSIDE EPOXY RESIN INJECTION	3.5 LIN.FT.			_	
	_				

UNDERSIDE OF DECK REPAIR QUANTITIES REPRESENT ESTIMATED VALUES OF DECK REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM OF 2"CLEAR TO SAWCUT. SEE REPAIR DETAILS.

ANTICIPATED BEAM REPAIR LOCATIONS							
SPAN	BEAM	LOCATION	DIM "A"	DIM "B"	DIM "C"	DIM "D"	
Α	9	BENT 1	9″	4"			
Α	12	BENT 1	4"	-			
Α	15	BENT 1	7"	-			

BEAM REPAIR QUANTITY TABLE							
BEAM EN	REPAIR	PLATING	REPAIR	STIFFENER	R REPAIR	DIAPHRAG	M REPAIR
LB	S.	LB	S.	LE	3S.	L	BS.
ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL
0		12		11		0	

PROJECT NO. I-5746C

MECKLENBURG COUNTY

BRIDGE NO. 590326

DocuSigned by:

02EE938FAB674CS...

02EE938FAB674CS...

03EESSOL...

SEAL

35647

10CINEER

COLUMN

A. COLUMN

A. COLUMN

A. COLUMN

C

8/23/2021

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION
RALEIGH

UNDERSIDE DECK REPAIR

SPAN A

REVISIONS SHEET NO.

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2 4 4 274

SHEET 1 OF 3