



BENT 1 NORTHBOUND

ELEVATION

R.L. PUTEK DATE : 05/2021 DRAWN BY : _ DATE : 05/2021 H. A. LOCKLEAR CHECKED BY:

END VIEW

DocuSigned by:
02EE938FAB674C5...

8/23/2021

AS-BUILT REPAIR QUANTITY TABLE QUANTITIES BENT 1 NORTHBOUND ESTIMATE ACTUAL AREA SQ.FT. VOLUME CU.FT. VOLUME CU.FT. AREA SHOTCRETE REPAIRS SQ.FT. CAP 18.2 9.1 29.1 58.2 COLUMNS AREA SQ.FT. VOLUME CU.FT. AREA VOLUME CONCRETE REPAIRS SQ.FT. SQ.FT. CAP 1.9 1.0 LIN. FT LIN. FT EPOXY RESIN INJECTION CAP 0.0 0.0 COLUMNS SQ. FT. SQ. FT. EPOXY COATING TOP OF BENT CAP 0

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. FOR REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

NOTES

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIR, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR, SEE SPECIAL PROVISIONS.

CLEAN AND REMOVE DEBRIS FROM THE TOP OF THE CAP. EPOXY COATING SHALL BE APPLIED TO THE TOP SURFACE OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY PLATES. FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

FOR PEDESTAL WALL REPAIR, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

SHOTCRETE REPAIR AREA

CONCRETE REPAIR AREA

---- EPOXY RESIN INJECTION (ERI)

PROJECT NO. I-5746C MECKLENBURG COUNTY BRIDGE No. 590330

SHEET 2 OF 2

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

> BENT 1 NORTHBOUND SPAN B FACE

> > SHEET NO

S9-14

TOTAL SHEETS 274

REVISIONS NO. BY: DATE: DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

23-AUG-2021 12:01 R:\Structures\FINAL PLANS\Bridge 330\409_027_I5746C_SMU_B1BNB_S9-14_590330.dgn