

AS-BUILT REPAIR	QUAN	ITIT,	Υ ΤΑ	BLE	
END BENT 1		QUANTITIES			
END DENT I	ESTI	MATE ACT		TUAL	
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.	
CAP & CURTAIN WALL	4.6	1 <b>.</b> 5			
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.	
CAP	1.0	0.3			
EPOXY RESIN INJECTION		LIN. FT.		LIN. FT.	
CAP & CURTAIN WALL		3.0			
EPOXY COATING		SQ. FT.		SQ. FT.	
CAP		132			

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. FOR REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

## NOTES

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIR, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CLEAN AND REMOVE DEBRIS FROM THE TOP OF THE CAP AND APPLY EPOXY PROTECTIVE COATING. EPOXY COATING SHALL BE APPLIED TO THE TOP SURFACE OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY PLATES. FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

SHOTCRETE REPAIR AREA

CONCRETE REPAIR AREA

EPOXY RESIN INJECTION (ERI)

PROJECT NO. I-5746C MECKLENBURG COUNTY BRIDGE NO. 590332

SHEET 1 OF 2

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

END BENT 1

SEAL 35647 NOINEER

8/23/2021		
DOCUMENT NOT CONSTDERED	NO.	BY:
DOCUMENT NOT CONSIDERED FINAL UNLESS ALL	1	
STGNATURES COMPLETED	2	

SHEET NO REVISIONS NO. BY: DATE: S10-29 DATE: TOTAL SHEETS 274

R.L.PUTEK \_ DATE : <u>06/2021</u> DRAWN BY : \_\_\_ DATE : 06/2021 H. A. LOCKLEAR CHECKED BY : \_