


				_
AS-BUILT REPAIR	QUAN	1 T T L	Y TA	E
END BENT 1		QUANTITIES		
END DENT I	ESTI	ACTL		
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.		
CAP & CURTAIN WALL	5.4	1.8		
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	
САР	4.6	1.5		Γ
EPOXY RESIN INJECTIO	LIN. FT.			
CAP & CURTAIN WALL		3.0		
EPOXY COATING	SQ. FT.			
САР		135		[
				ſ

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1" BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. FOR REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

DRAWN BY :	R.L.PUTEK	DATE : <u>06/2021</u>
CHECKED BY :	H. A. LOCKLEAR	DATE : <u>06/2021</u>

+

ELEVATION



NOTES

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.


CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIR, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CLEAN AND REMOVE DEBRIS FROM THE TOP OF THE CAP AND APPLY EPOXY PROTECTIVE COATING.EPOXY COATING SHALL BE APPLIED TO THE TOP SURFACE OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY PLATES.FOR EPOXY COATING, SEE SPECIAL PROVISIONS.



SHOTCRETE REPAIR AREA

CONCRETE REPAIR AREA

CONTRESIN INJECTION (ERI)

	PROJEC ME BRIDGE	CKLEN	νBι	JRC	•	UNTY	
SHEET 2 OF 2							
DocuSigned by: 02EE938FAB674C5	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH						
OR SEAL SEAL 35647	END BENT 1						
8/23/2021	REVISIONS SHEET NO.						
						S10-30	
DOCUMENT NOT CONSIDERED FINAL UNLESS ALL	1		3			TOTAL SHEETS	
SIGNATURES COMPLETED	2		4			274	