

AS-BUILT REPAIR QUANTITY TABLE							
BENT 15	QUANTITIES						
	ESTI	ΜΑΤΕ	ACTUAL				
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT	VOLUME CU.FT.			
САР	0.0	0.0					
COLUMNS & STRUTS	0.0	0.0					
CONCRETE REPAIRS	AREA SQ.FT	VOLUME CU.FT.	AREA SQ.FT	VOLUME CU.FT.			
САР	0.0	0.0					
EPOXY RESIN INJECTION		LIN.FT		LIN.FT			
САР	0.0						
COLUMNS & STRUTS		0.0					

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1" BEHIND REBAR AND 2" MIN.CLEAR TO SAWCUT. FOR REPAIR DETAILS, SEE ``TYPICAL CAP AND COLUMN REPAIR DETAIL"SHEET.

NOTES

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIR, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR, SEE SPECIAL PROVISIONS.

SHOTCRETE REPAIR AREA 

CONCRETE REPAIR AREA  $\bigotimes$ 



 $\sim$  EPOXY RESIN INJECTION (ERI)

	PROJEC	T NO.	<u> </u>	-5746	С		
			NBURG		UNTY		
	BRIDGE NO: <u>590332</u>						
DocuSigned by:	SHEET 4 OF	5					
02EE938FAB674C5 02EE938FAB674C5 07 07 07 07 07 07 07 07 07 07	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH						
	BENT 15 SPAN S FACE						
			SHEET NO.				
OCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY:	DATE:	S10-102		
FINAL UNLESS ALL SIGNATURES COMPLETED	1		3 4		total sheets 274		