

8/25/2021 I5939\_SMU\_SP01\_770012.dgn fflores

AS-BUILT REPAIR QUANTI	TY T	ABLE
	ESTIMATE	ACTUAL
SLOPE PROTECTION VOID FILLING	500 LBS.	
SILICONE JOINT SEALANT FOR SLOPE REPAIRS	100 LF	

## NOTES:

AFTER COMPLETION OF VOID FILLING, SEAL CRACKS IDENTIFIED WITH POURABLE SILICONE JOINT SEALANT AS DESCRIBED IN THE SPECIAL PROVISION FOR SILICONE JOINT SEALANT FOR SLOPE REPAIRS (BACKER RODS MAY BE OMITTIED AS APPROVED BY THE ENGINEER).

FOR SLOPE PROTECTION VOID FILLING, SEE SPECIAL PROVISIONS.

FOR SILICONE JOINT SEALANT FOR SLOPE REPAIRS, SEE SPECIAL PROVISIONS.

project no. <u>I-5939</u> <u>Robeson</u> county bridge no. <u>770012</u>							
Jacola Kala CARO 29 00 00 54 00 SS / 01	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH						
SEAL 043777 <sup>1/</sup> G INE <sup>FR</sup> 8/25/2021	SLOPE PROTECTION Repairs						
KCA							
<b>KISINGER CAMPO</b>	REVISIONS			SHEET NO.			
RED <b>301 FAYETTEVILLE ST., SUITE 1500</b>	NO. BY:	DATE:	NO. BY:	DATE:	S2-7		
RALEIGH, NC 27601 (919) 882-7839	1		3 4		total sheets 12		
	ß		<sup>4</sup> 7				