

6988: Replace 30 LF of sidewalk behind ramp to repair and fix slope to the best extent possible.


6987: Align with ramp 6988

Curb Ramps To Be Repaired

- Retrofit
- Remove and Replace
- New Curb Ramp
- Remove Ramp


Municipal Boundary

NCHPO Historic Boundary (NR and LHD)



2023 East
WBS: 2022CPT.05.13.20921.1

Sinclair Dr
from US 401 to End Maint

 NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
DIVISION 5

Source: NV5 Engineers and Consultants Inc., ESRI, NC OneMap, NCDOT, NCHPO