

jduke

AS-BUILT REPAIR QUANTITY TABLE									
	QUANTITIES								
	ESTI	MATE	ACTUAL						
HOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.					
CAP/FOOTING	_	-							
COLUMN/PILE	_	-							
ONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.					
* CAP	_	-							
POXY RESIN INJECTION	LIN.FT.		LIN.FT.						
САР	_								
COLUMN/PILE	_								
FOOTING	144.0								
P INTEGRAL PILE JACKETS	LIN.FT.		LIN.FT.						
PILE									

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE. MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS, SEE "CONCRETE RESTORATION DETAILS" SHEETS.

## NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE TABLE ABOVE.

CRACKING LOCATIONS AND QUANTITIES FOR LOCATIONS DESCRIBED AS "SCATTERED THROUGHOUT" IN THE INSPECTION REPORT ARE BASED ON THE BEST INFORMATION AVAILABLE. THE ENGINEER AND CONTRACTOR SHALL IDENTIFY AND REPAIR ALL CRACKS >=1/16" AS DESCRIBED IN THE SPECIAL PROVISIONS AT EACH BENT.

AVERAGE CONCRETE COVER IS EXPECTED TO BE FROM 2"TO 3" ON THE CAP AND FROM  $1\frac{1}{2}$ " TO 2" ON THE PILES. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING EXCAVATION AND DEMOLITION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE "CONCRETE RESTORATION DETAILS" SHEETS.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

REPAIRS TO THE BENT CAP MAY REQUIRE BRIDGE JACKING.FOR BRIDGE JACKING, SEE SPECIAL PROVISIONS.

FOR EPOXY COATING, SEE SPECIAL PROVISIONS AND STANDARD SPECIFICATIONS SECTION 420-18.

		PROJEC Bridge	DAR	E		<u>PR.4</u> co 0012	6 UNTY		
	Docusioned by: CARO Juckes Juckss Joy Jucks 29530Celles4D9 SEAL 043777 MG INE EN 10/19/2021	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH SUBSTRUCTURE REPAIRS							
	KCA	BENTS 19							
	<b>KISINGER CAMPO</b>	REVISIONS					SHEET NO.		
RED	<b>&amp; ASSOCIATES</b> 301 FAYETTEVILLE ST., SUITE 1500	NO. BY:	DATE:	NO. BY:		DATE:	S-84		
	RALEIGH, NC 27601 (919) 882-7839	1		I			TOTAL SHEETS		
ED	NC FIRM LICENSE: C-1506	2		<b>4</b>			137		