



ן
SPAN H
SPAN G





SPAN H SPAN G



AS-BUILT REPAIR QUANTITY TABLE						
	QUANTITIES					
BENT 7 SPAN H FACE	ESTIMATE		ACTUAL			
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.		
САР	0.0	0.0				
COLUMN	0.0	0.0				
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.		
САР	0.0	0.0				
COLUMN	0.0	0.0				
EPOXY RESIN INJECTION		LIN.FT.	LIN.FT.			
САР		0.5				
COLUMN		0.0				
ALLIES TN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER						

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE ``TYPICAL CAP AND COLUMN REPAIR DETAILS'' SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE REPAIRS MAYBE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

SHOTCRETE REPAIR AREA



CONCRETE REPAIR AREA

ERI - EPOXY RESIN INJECTION



PROJECT NO. <u>15BPR.21</u> <u>MONTGOMERY</u> county BRIDGE NO. <u>610006</u>

DocuSigned by: Krishna P. Sedai EAGF 7941500 TH CAROL OF ESSION SEAL 031583 PRASAD 11/18/2021	DEPARTMENT OF TRANSPORTATION RALEIGH BENT 7 SPAN H FACE					
	REVISIONS SHEET NO.					
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY:	DATE:	S1-26	
FINAL UNLESS ALL	1		3		TOTAL SHEETS	
SIGNATURES COMPLETED	2		4		34	