

SPAN A

AS-BUILT REPAIR QUANITY TABLE

DECK SURFACE REPAIR SPAN A

ESTIMATE ACTUAL

CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT

SHOTBLASTING BRIDGE DECK

SILANE DECK TREATMENT

481.0 SQ. YDS.


NOTES:

TOP OF DECK REPAIR QUANTITIES REPRESENT ESTIMATED VALUES OF CLASS II SURFACE PREPARATION AND CONCRETE DECK REPAIR AFTER REMOVAL OF UNSOUND CONCRETE. (MIN. 2" CLEAR TO SAWCUT). SEE CONCRETE FOR DECK REPAIR SPECIAL PROVISION.

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

FOR "CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT", SEE SPECIAL PROVISIONS.

FOR SECTIONS A-A AND B-B, SEE "JOINT DETAILS" SHEET.



CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT



BRIDGE JOINT DEMOLITION

PROJECT NO. 15BPR.55

FORSYTH COUNTY

BRIDGE NO. 330078

SHEET 1 OF 4

O1/26/2022

O1/26/2022

OSEAL

O3I583

PRASADIMINATION

Docusigned By Marine Marine P. Sedai

DEPARTMENT OF TRANSPORTATION
RALEIGH

DECK SURFACE REPAIR

SPAN A

REVISIONSSHEET NO.DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETEDNO.BY:DATE:NO.BY:DATE:S1-0413TOTAL SHEETS
32479

DRAWN BY: ______ E.BAYISSA DATE: 12/2019
CHECKED BY: _____ A.SORSENGINH DATE: 07/2021

1/25/2022 P:\15BPR55\Structures\Final Plans\401_007_15BPR.55_SMU_DSR_S04_330078.dgn ksedai