





AS-BUILT REPAIR QUANTITY TABLE

REPAIRS BENT 1 - SPAN B	QUANTITIES								
	ESTI	MATE	ACTUAL						
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF					
САР	3.0	1.5							
COLUMN	1.0	0.5							
STRUT	0	0							
CONCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF					
САР	0	0							
COLUMN	0	0							
STRUT	0	0							

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1" BEHIND REBAR AND MIN. 1" CLEAR TO SAWCUT. SEE REPAIR DETAILS.

NOTES

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE REPAIRS MAYBE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS.



SHOTCRETE REPAIR AREA



CONCRETE REPAIR AREA



AREA PREVIOUSLY ACCOUNTED FOR ON ADJACENT FACE

	PROJEC	T NO.	15	15BPR.49				
		WAKI		CO	UNTY			
	BRIDGE	NO	9	10240				
	SHEET 3 OI	- 12						
NUMBER CAROLANI	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH							
SEAL 2 037479	SUBSTRUCTURE REPAIRS							
DocuSigned by: Nichobas Pierce		E SPA	BENT N B F	1 FACE				
15110B434D0B485 01/21/2022	REVISIONS SHEET NO.							
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY:	DATE:	S2-24			
FINAL UNLESS ALL SIGNATURES COMPLETED	12		3 4		total sheets 73			