



NOTES

1. REMOVE EXISTING SPLICE ENCLOSURE AFTER CUTOVER TO NEW FIBER.
2. INSTALL MOLDABLE DUCT SEAL ON ALL CONDUITS CONTAINING FIBER OPTIC CABLE AND FEEDER CONDUCTORS.

**DOCUMENT NOT CONSIDERED FINAL
UNLESS ALL SIGNATURES COMPLETED**

<p>750 N. Greenfield Pkwy., Garner, NC 27529</p>	<p>ITS DEVICE REPLACEMENT</p>		
	<p>DIVISION 05 WAKE CO.</p> <p>PLAN DATE: NOVEMBER 2021</p> <p>PREPARED BY: J. WALDEN</p>	<p>REVIEWED BY: A. J. SKUCE, PE</p> <p>REVIEWED BY:</p>	
<p>DATE: NOV 30, 2021</p>			<p>DATE</p>