

AS-BUILT REPAIR QUANTITY TABLE						
BENT 3 SPAN C FACE		QUANTITIES				
BENT 5 STAN CTACE	ESTI	ΜΑΤΕ	ACTUAL			
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.		
САР	1.7	0.9				
COLUMN	0.0	0.0				
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.		
САР	0.0	0.0				
COLUMN	0.0	0.0				
EPOXY RESIN INJECTION		LIN.FT.	LIN.FT.			
САР	0.0					
COLUMN	0.0					
EPOXY COATING	SQ.FT.					
ENDS OF CAP	204.0					

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE ``TYPICAL CAP AND COLUMN REPAIR DETAILS'' SHEET SD-01.

NOTES

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

SHOTCRETE REPAIRS MAYBE SUBSTITUTED IN LIEU OF CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

EPOXY COATING SHALL BE APPLIED AT ENDS OF CAP AND SHALL INCLUDE 3"MINIMUM TO TOP AND BOTTOM OF CAP.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

FOR "TYPICAL CAP AND COLUMN REPAIR DETAILS," SEE SHEET SD-01.

SHOTCRETE REPAIR AREA

TH CARA

FESSION,

SEAL 031021

CONCRETE REPAIR AREA

 $\sim\sim$

ERI - EPOXY RESIN INJECTION

PROJECT NO.	I-5831A
MADIS	ON COUNTY
BRIDGE NO	560547

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

BENT 3				
SPAN	С	FACE		

DocuSigned by: Ambut Male BOURSAAEEEADUSA							
03748522622484			REVI	SION	IS		SHEET NO.
DOCUMENT NOT CONSIDERED	N0.	BY:	DATE:	NO.	BY:	DATE:	S3-20
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			24