NOTES


REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

FOR SECTION A-A. SEE "JOINT REPAIR DETAILS" SHEET.


FOR CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

NO REPAIRS ARE PROPOSED FOR THE APPROACH SLABS.







PLAN (SPANS A THRU E AND APPROACH SLABS) BRIDGE NO. 060027 STATE OF NORTH CAROLINA

___ COUNTY

BEAUFORT

DEPARTMENT OF TRANSPORTATION
RALEIGH SEAL 26445 CINEER O

P. Korey Newton 4FFE39D1431B407

SUPERSTRUCTURE

DECK SURFACE REPAIR

REVISIONS SHEET NO. S2-3 NO. BY: DATE: DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED TOTAL SHEETS

__ DATE : <u>05/2021</u> __ DATE : <u>07/2021</u> S. T. SANDOR DRAWN BY : . W.C.SMITH CHECKED BY :