

AS-BUILT REPAIR QUANTITY TABLE QUANTITIES ESTIMATE ACTUAL VOLUME AREA **VOLUME** SQ. FT. CU.FT. SQ.FT. CU.FT. 0.0 0.0 4.0 2.0 VOLUME SQ.FT. CU.FT. SQ.FT. CU.FT. 0.0 0.0 0.0 0.0 EPOXY RESIN INJECTION LIN.FT. LIN.FT. 0.0 0.0

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR

CONCRETE REPAIRS MAYBE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

FOR CAP AND COLUMN REPAIRS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" AND "PRESTRESSED CONCRETE PILE REPAIR DETAILS" SHEETS.

SHOTCRETE REPAIR AREA

CONCRETE REPAIR AREA

ERI - EPOXY RESIN INJECTION

PILE NUMBER

PROJECT NO. 15BPR.56 BEAUFORT COUNTY BRIDGE NO. 060027

> STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

> > SUBSTRUCTURE

BENT 3 REPAIR

SHEET NO. **REVISIONS** NO. BY: S2-8 DATE: DATE: TOTAL SHEETS