



AS-BUILT REPAIR QUANTITY TABLE DECK SURFACE REPAIRS - SPANS 8 THROUGH 11 ESTIMATE ACTUAL 1,187.6 SQ. YDS. SHOTBLASTING BRIDGE DECK SILANE DECK TREATMENT 1,187.6 SQ. YDS. CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT 0.0 SQ.FT. BARRIER RAIL REPAIRS ESTIMATE ACTUAL EPOXY RESIN INJECTION O.O LIN.FT. JOINT REPAIR ESTIMATE ACTUAL BRIDGE JOINT DEMOLITION 64.0 SQ.FT.

NOTES

FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

FOR CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

FOR SECTION B-B, SEE "JOINT REPAIR DETAILS" SHEET.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

FOR BRIDGE JOINT DEMOLITION, SEE SPECIAL PROVISIONS.

SHOTBLASTING AND SILANE DECK TREATMENT AREA

ERI - EPOXY RESIN INJECTION

BRIDGE JOINT DEMOLITION

SEAL 7 26445 PROJECT NO. 15BPR.56

BEAUFORT COUNTY

BRIDGE NO. 060077

SHEET 3 OF 10

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

SUPERSTRUCTURE

PLAN OF SPANS

1/24/2022 R:\Structures\Plans\Bridge_060077\404_019_15BPR56_SMU_DSR3_010_060077.dgn pknewton

__ DATE : <u>07/2021</u>

_ DATE : <u>12/2021</u>

S. T. SANDOR

W.C.SMITH

DRAWN BY : .

CHECKED BY :