

AS-BUILT REPAIR QUANTITY TABI	E							
DECK SURFACE REPAIRS - SPANS 16 THROUGH 19								
ESTIMATE ACTL	AL							
SHOTBLASTING BRIDGE DECK 1,329.8 SQ. YDS.								
SILANE DECK TREATMENT 1,329.8 SQ. YDS.								
CONCRETE DECK REPAIR FOR SILANE 0.0 SQ.FT. DECK TREATMENT								
BARRIER RAIL REPAIRS								
ESTIMATE ACTUA	ACTUAL							
EPOXY RESIN INJECTION O.O LIN.FT.								
JOINT REPAIR								
ESTIMATE ACTUA	_							
BRIDGE JOINT DEMOLITION 64.0 SQ.FT.								

NOTES

FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS. FOR CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS. FOR SECTION B-B, SEE ``JOINT REPAIR DETAILS' SHEET. FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS. FOR BRIDGE JOINT DEMOLITION, SEE SPECIAL PROVISIONS.

	SHOTBLASTING AND SILANE DECK TREATMENT AREA
\sim	ERI - EPOXY RESIN INJECTION
	BRIDGE JOINT DEMOLITION

		CT NO. EAUF		<u>BPR.5</u> C0			
	BRIDGE NO. 060077						
SHEET 5 OF 10							
NUMBER OF AROLANS	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH						
SEAL 26445	SUPERSTRUCTURE						
DocuSigned by:		PLAN	OF	SPANS	5		
P. Korey Newton							
4FFE39D1431B407 01/27/2022	REVISIONS SHEET NO.						
OCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY:	DATE:	S4-12		
FINAL UNLESS ALL SIGNATURES COMPLETED	1		3 4		TOTAL SHEETS 17		