



AS-BUILT REPAIR QUANTITY TABLE DECK SURFACE REPAIRS - SPANS 20 THROUGH 23 ESTIMATE ACTUAL 1,329.8 SQ. YDS. SHOTBLASTING BRIDGE DECK SILANE DECK TREATMENT 1,329.8 SQ. YDS. CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT 0.0 SQ.FT. BARRIER RAIL REPAIRS ESTIMATE ACTUAL EPOXY RESIN INJECTION O.O LIN.FT. JOINT REPAIR

ESTIMATE

64.0 SQ.FT.

ACTUAL

NOTES

BRIDGE JOINT DEMOLITION

FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

FOR CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

FOR SECTION B-B, SEE "JOINT REPAIR DETAILS" SHEET.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

FOR BRIDGE JOINT DEMOLITION, SEE SPECIAL PROVISIONS.

SHOTBLASTING AND SILANE DECK TREATMENT AREA

 \sim ERI - EPOXY RESIN INJECTION

BRIDGE JOINT DEMOLITION

PROJECT NO. 15BPR.56

BEAUFORT COUNTY
BRIDGE NO. 060077

SHEET 6 OF 10

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

SUPERSTRUCTURE

DocuSigned by:

P. Korey Newton

4FFE39D1431B407...

SEAL 26445

: NGINEEP

PLAN OF SPANS

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2 REVISIONS SHEET NO. BY: DATE: No. BY: DATE: SHEETS

17

1/24/2022
R:\Structures\Plans\Bridge_060077\404_025_15BPR56_SMU_DSR6_013_060077.dgn
pknewton

S. T. SANDOR

W.C.SMITH

DRAWN BY : .

CHECKED BY :

_ DATE : <u>07/2021</u>

_ DATE : <u>12/2021</u>