

+

+

## NOTES

FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS. FOR CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS. FOR SECTION B-B, SEE ``JOINT REPAIR DETAILS' SHEET.

AS-BUILT REPAIR	QUANTIT	Y TABLE
DECK SURFACE REPAIRS - SPANS I THRU L		
	ESTIMATE	ACTUAL
SHOTBLASTING BRIDGE DECK	1,333.3 SQ. YDS.	
SILANE DECK TREATMENT	1,333.3 SQ. YDS.	
CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT	0.0 SQ.FT.	
BRIDGE JOINT DEMOLITION	60.0 SQ.FT.	

SHOTBLASTING BRIDGE DECK AND SILANE DECK TREATMENT AREA 

ERI - EPOXY RESIN INJECTION  $\sim$ 

BRIDGE JOINT DEMOLITION  $\overline{}$ 

DINT	PROJECT NO. <u>15BPR.56</u> PITT COUNTY		
	BRIDGE NO. 730127		
SHEET 3 OF 5			
TH CAROLAND	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH		
SEAL 26445	SUPERSTRUCTURE		
THEY NEW WINNING	PLAN OF SPANS		
P. Korey Newton			
4FFE39D1431B407 02/23/2022	REVISIONS SHEET NO.		
DOCUMENT NOT CONCEREDED	NO. BY: DATE: NO. BY: DATE: \$5-11		
DOCUMENT NOT CONSIDERED FINAL UNLESS ALL	1 3 TOTAL SHEETS		
SIGNATURES COMPLETED	<b>2</b>		