

+

+

 $\Box$ - SHOTCRETE REPAIR AREA B\* BEAM NUMBER (W) WEB PLATING REPAIR (S) STIFFENER REPAIR (F) BOTTOM FLANGE PLATING REPAI

- CONCRETE REPAIR AREA

 $\boxtimes$ 

- BW BOLTED WEB PLATE REPAIR
- BF BOLTED FLANGE PLATE REPAIR
- BE BEAM END CUT-OUT REPAIR

STEEL REPAIR LOCATIONS								
REPAIR TYPE	SPAN	BEAM	LOCATION	DIM. ``A''	DIM.``B''	DIM.``C''	DIM.``D''	
BW	В	3	BENT 1	8½″	10″	-	-	
BW	В	7	BENT 1	8½″	10″	_	-	
S	В	7	BENT 1	4″	-	-	-	

(SEE SHEETS S3-22 THRU S3-24 FOR BEAM REPAIR DETAILS AND DIMENSIONS.)

	BEAM REPAIR QUANTITIY TABLE								
BOLTED STEE	L PLATES	STEEL PL	ATES	STIFFE	NER	STEEL DIAF	PHRAGM	BEAM END	CUT-OUT
LBS.	•	LBS.		LBS.	•	LBS.		LBS.	J
ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL
107.2		19.1		3.7		0		0	
STEEL	KEEPER A	NGLE ASSEMB	LY		-				
EA.									
ESTIMATE ACTUAL									
0									15RPF

	REPAIR QUANTITY TABLE						
	UNDERSIDE OF DECK	QUANTITIES					
	REPAIRS - SPAN B	ESTI	MATE	ACT	UAL		
	SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF		
	UNDERSIDE OF DECK	1.0	0.5				
	CONCRETE BENT DIAPHRAGM	5.3	2.7				
	OVERHANG	2.8	1.0				
AIR	CONCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF		
	UNDERSIDE OF DECK	0.0	0.0				
2	CONCRETE BENT DIAPHRAGM	0.0	0.0				
	OVERHANG	0.0	0.0				

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.

## NOTES:

THE LOCATIONS AND DIMENSIONS OF THE AREAS FOR REPAIR ARE BASED ON THE BEST INFORMATION AVAILABLE.THE CONTRACTOR, IN CONJUNCTION WITH THE ENGINEER, SHALL VERIFY THE LOCATION AND EXTENT OF REPAIR AREAS PRIOR TO STEEL FABRICATION. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE REPAIR QUANTITY TABLE.

FOR ADDITIONAL NOTES, SEE SHEET 1 OF 5.

	PROJEC	<u>BPR.4</u> co 0039	17 )UNTY				
	SHEET 2 OF 5						
SEAL O30024 BocuSigned by: USter Abraha O5/26/2022	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH UNDERSIDE DECK REPAIRS SPAN B						
	REVISIONS SHEET NO NO. BY: DATE: NO. BY: DATE: S3-10						
DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED	no. by: 1 2	DATE:	NO. ВҮ: З 4	DATE:	S3-10 TOTAL SHEETS 33		