

			NOTE:
DRAWN BY : Checked by :	M. SPENCER J. FARNHAM	DATE : <u>12/2018</u> DATE : <u>03/2019</u>	REPAIR LOCATIONS AND ESTIMATED QUANTITIES AR NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSAF APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIR QUANTITY TABLE.
-			

+

+

\$\$\$\$\$\$\$\$\$\$\$\$\$\$\$\$\$\$\$DGN\$\$\$\$\$\$\$\$\$\$\$\$\$\$\$\$

ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS GARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE HE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT



SUMMARY OF QUANTITIES	FOR SPA	AN 1
	ESTIMATE	ACTUAL
SHOTCRETE REPAIRS (UNDERDECK)	-	
BRIDGE JOINT DEMOLITION	_	
CLASS II SURFACE PREPARATION	_	
CLASS III SURFACE PREPARATION	3.0 SY	
CONCRETE DECK REPAIR FOR MMA OVERLAY	14.7 CF	
CRACK PRETREATMENT	_	
CONCRETE BRIDGE DECK CRACK SEALING	105.5 SY	
MMA OVERLAY SYSTEM	949.0 SF	

SHOTCRETE REPAIRS (UNDERDECK)					
BRIDGE JOINT DEMOLITION CLASS II DECK REPAIR	project no. <u>HB-0017</u> DARE county				
- MMA Overlay system	BRIDGE NO. 270009				
CRACK PRETREATMENT	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH				
PRETREATMENT PRETREATMENT PRETREATMENT PRETREATMENT PRETREATMENT PRETREATMENT PRETREATMENT PRETREATMENT	SURFACE PREPARATION & UNDERDECK REPAIRS SPAN 1				
DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED	REVISIONS SHEET NO. NO. BY: DATE: NO. BY: DATE: S-18 1 3 3 5 355				