

+

+

	SUMMARY	OF QUANTITIES	FOR SPAN	74
N 76			ESTIMATE	ACTUAL
	SHOTCRETE REPAIRS		2.6 CF	ACTORE
	BRIDGE JOINT DEMOLITION			
	CLASS II SURFACE PREPARATION			
			_	
	CLASS III SURFACE		_	
		AIR FOR MMA OVERLAY	_	
	CRACK PRETREATMEN	Т	19.3 LF	
	CONCRETE BRIDGE D	ECK CRACK SEALING	112.0 SY	
	MMA OVERLAY SYSTE	M	1008.0 SF	
		OF QUANTITIES	FUR SPAN	C) /
			ESTIMATE	ACTUAL
	SHOTCRETE REPAIRS	(UNDERDECK)	_	
	BRIDGE JOINT DEMO	LITION	11.0 SF	
	CLASS II SURFACE PREPARATION		_	
	CLASS III SURFACE	PREPARATION	_	
	CONCRETE DECK REP,	AIR FOR MMA OVERLAY	_	
	CRACK PRETREATMEN	T	19.3 LF	
	CONCRETE BRIDGE D	FCK CRACK SFALTNG	112.0 SY	
	MMA OVERLAY SYSTE		1008.0 SF	
			1000.0 31	
	SUMMARY OF QUANTITIES		FOR SPAN	76
			ESTIMATE	ACTUAL
	SHOTCRETE REPAIRS			ACTORE
			11.0.55	
	BRIDGE JOINT DEMOLITION		11.0 SF	
	CLASS II SURFACE PREPARATION		_	
	CLASS III SURFACE PREPARATION		-	
	CONCRETE DECK REPAIR FOR MMA OVERLAY		_	
	CRACK PRETREATMEN	T	77.0 LF	
AN 78 ►►	CONCRETE BRIDGE D	ECK CRACK SEALING	112.0 SY	
	MMA OVERLAY SYSTE	M	1008.0 SF	
	SUMMARY OF QUANTITIES		FOR SPAN	
			ESTIMATE	ACTUAL
	SHOTCRETE REPAIRS (UNDERDECK)		8.6 CF	
	BRIDGE JOINT DEMOLITION		11.0 SF	
	CLASS II SURFACE	_		
	CLASS III SURFACE PREPARATION		_	
	CONCRETE DECK REPAIR FOR MMA OVERLAY		_	
	CRACK PRETREATMENT		57.8 LF	
	CONCRETE BRIDGE DECK CRACK SEALING		112.0 SY	
	MMA OVERLAY SYSTEM		1008.0 SF	
			100010 01	
	_ SHOTCRETE REPAIRS (UNDERDECK)	Ŝ		
	BRIDGE JOINT			
	DEMOLITION	PROJECT NO	HB-00	17
	_ CLASS II deck repair			<u> </u>
	CLASS III	DARE	C	OUNTY
	DECK REPAIR		27000	9
	_ MMA	BRIDGE NO		
	OVERLAY SYSTEM			
	DEPARTMENT OF RAI DEPARTMENT OF RAI DEPARTMENT OF RAI DEPARTMENT OF RAI SEAL O20208 SEAL O20208 SEAL O20208 SEAL O20208 SEAL SURFACE PE & UNDERDE SPANS 74		NORTH CAROLINA TRANSPORTATION	
			REPARATION CK REPAIRS 4 THRU 77	
			· · ·	
	ACB8082119D74CD			SHEET NO.
we		REVICTONC)	- II OLU I I IVII -
	IENIT NIAT CANCTARA	REVISIONS	BY: DATE:	S-37
DOCUM	IENT NOT CONSIDERED INAL UNLESS ALL NATURES COMPLETED			<u> </u>