

+

+

AS-BUILT REPAIR QUANTITY TABLE									
BENT 17									
CAP REPAIRS	ESTI	MATE							
SHOTCRETE REPAIRS	- SF	- CF	SF	CF					
EPOXY RESIN INJECTION	_	LF		LF					
PILE REPAIRS	ESTI	MATE							
PILE CONCRETE RESTORATION	10.0 SF	4.2 CF	SF	CF					
FRP PROTECTIVE SYSTEM AWL	132.	5 SF							
FRP PROTECTIVE SYSTEM BWL	66.0) SF							
B	ENT 1	8							
CAP REPAIRS	ESTI	MATE							
SHOTCRETE REPAIRS	- SF	- CF	SF	CF					
EPOXY RESIN INJECTION	- LF			LF					
PILE REPAIRS	ESTI	MATE							
PILE CONCRETE RESTORATION	8.6 SF	3.9 CF	SF	CF					
FRP PROTECTIVE SYSTEM AWL	166.0) SF							
FRP PROTECTIVE SYSTEM BWL	66.0) SF							

FOR CAP REPAIRS: VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2" CL. TO SAWCUT. SEE REPAIR DETAILS. NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR DETAILS, SEE ``TYPICAL CAP, COLUMN & UNDERDECK REPAIR DETAILS'' & ``PILE CONCRETE RESTORATION DETAILS'' SHEETS. FOR PILE CONCRETE RESTORATION, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM DETAILS AND UNDERWATER MORTAR REPAIRS, SEE ``PILE FRP PROTECTIVE SYSTEM DETAILS'' SHEET.

NE	ESTIMATED PILE CRACK QTY.									
N			NW	W	SW	S	SE	E	NE	Ν
NW SW	w BENT 17	PILE 1	_	2	-	_	-	_	_	2
W		PILE 2	_	4	4	_	_	_	_	-
		PILE 3	5	-	-	-	-	-	6	5
		PILE 4	1	_	_	_	_	_	_	-
		PILE 1	_	_	_	_	3	_	3	5
TEM BELOW .ude	BENT 18	PILE 2	_	-	5	3	-	6	3	3
R MORTAR		PILE 3	3	-	_	-	-	-	2	-
		PILE 4	-	_	-	-	-	_	4	8
	NOTE: FOR IN	IFORMATIO	N ON	PIL	E CO	NDIT	ION	ONL`		
	ł	PROJEC		NO.			3-())	17	
N INJECTION			\Box	AR	F			\sim	$\cap \square$	$I \pm V$
TIVE SYSTEM	-			\square						νTΥ
TE RESTORATION	[BRIDGE)		2	70()()	9	
REPAIRS										
STATE OF NORTH CAROLINA							NC			
DocuSigned by: Eti B That ACB8082119D74C	h 7/14/2022	BE	NΤ	1-	78	X	BE	NT	1	8
ue				REVIS	SIONS					EET NO.
DOCUMENT NOT FINAL UNLE SIGNATURES (CONSIDERED ESS ALL	NO. ВҮ: 1 2	DAT	E:	>>0. ੴ ∰	BY:	D	ATE:		S-124 ^{total} sheets 355