

+

+

AS-BUILT REPA	AIR QU	JANTI	τγ τα	BLE					
BENT 63									
CAP REPAIRS									
SHOTCRETE REPAIRS	1.3 SF	0.7 CF	SF	CF					
EPOXY RESIN INJECTION	_	LF		LF					
PILE REPAIRS									
PILE CONCRETE RESTORATION	55.5 SF	21.4 CF	SF	CF					
FRP PROTECTIVE SYSTEM AWL	193.	4 SF							
FRP PROTECTIVE SYSTEM BWL	66.0) SF							
BENT 64									
CAP REPAIRS									
SHOTCRETE REPAIRS	- SF	- CF	SF	CF					
EPOXY RESIN INJECTION	- LF			LF					
PILE REPAIRS									
PILE CONCRETE RESTORATION	34.0 SF	13.7 CF	SF	CF					
FRP PROTECTIVE SYSTEM AWL	121.5 SF								
FRP PROTECTIVE SYSTEM BWL	49.5	5 SF							
END CAD DEDATES, VALUES THICH	ADT DEDDEC	CENIT ESTIMA	TED DEDAT	D TOTALS					

FOR CAP REPAIRS: VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2" CL. TO SAWCUT. SEE REPAIR DETAILS. NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR DETAILS, SEE ``TYPICAL CAP, COLUMN & UNDERDECK REPAIR DETAILS'' & ``PILE CONCRETE RESTORATION DETAILS'' SHEETS. FOR PILE CONCRETE RESTORATION, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM DETAILS AND UNDERWATER MORTAR REPAIRS, SEE ``PILE FRP PROTECTIVE SYSTEM DETAILS'' SHEET.

E	ESTIM	ATED PILE CRACK QTY. TABLE								
NE			NW	W	SW	S	SE	E	NE	N
		PILE 1	_	4	4	_	6	8	_	-
		PILE 2	-	5	7	—	7	5	-	_
NW		PILE 3	-	_	-	_	_	_	4	-
W		PILE 4	6	_	-	_	-	_	6	6
	BENT 64	PILE 1	_	_	_	_	_	_	_	_
TEM BELOW UDE		PILE 2	8	_	3	3	3	_	_	5
R MORTAR		PILE 3	3	-	4	-	-	-	-	5
		PILE 4	6	4	4	_	4	4	6	-
	NOTE:FOR IN	IFORMATIO	N ON	PIL	E CO	NDIT	ION	ONLY		
PROJECT NO. <u>HB-0017</u>										
DARE COUNTY							ΛΤΥ			
TIVE SYSTEM										
TE RESTORATION BRIDGE NO. 270009										
REPAIRS										
	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH									
BENT 63 & BENT 64										
le				REVIS	SIONS				SH	EET NO.
DOCUMENT NOT	CONSIDERED	NO, BY:	DAT	E:		BY:	D	ATE:		5-147
FINAL UNLESS ALL SIGNATURES COMPLETED		1			3 4				_	total sheets 355
					~~					555