

AS-BUILT REPAIR QUANTITY TABLE				
BENT 125				
CAP REPAIRS	ESTIMATE		ACTUAL	
SHOTCRETE REPAIRS	5.8 SF	2.9 CF	SF	CF
EPOXY RESIN INJECTION	- LF			LF
COLUMN REPAIRS	ESTIMATE		ACTUAL	
SHOTCRETE REPAIRS	3.2 SF	1.6 CF	SF	CF
EPOXY RESIN INJECTION	- LF		LF	
PILE REPAIRS	ESTIMATE		ACTUAL	
FRP PROTECTIVE SYSTEM AWL	- SF		SF	
FRP PROTECTIVE SYSTEM BWL	302.5 SF		SF	