



AS-BUILT REPA	AIR QU	JANTI	TY TA	BLE
BENT 140				
CAP REPAIRS	ESTIMATE		ACTUAL	
SHOTCRETE REPAIRS	- SF - CF		SF	CF
EPOXY RESIN INJECTION	- LF		LF	
COLUMN REPAIRS	ESTIMATE		ACTUAL	
SHOTCRETE REPAIRS	25.4 SF	12.7 CF	SF	CF
EPOXY RESIN INJECTION	- LF		LF	
PILE REPAIRS	ESTIMATE		ACTUAL	
FRP PROTECTIVE SYSTEM AWL	- SF		SF	
FRP PROTECTIVE SYSTEM BWL	544.5 SF		SF	

FOR CAP REPAIRS: VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR DETAILS, SEE ``TYPICAL CAP, COLUMN & UNDERDECK REPAIR DETAILS''& ``PILE CONCRETE RESTORATION DETAILS'' SHEETS.

FOR FOOTING, COLUMN, AND STRUT REPAIR DETAILS, SEE ``PILE FOOTING RESTORATION' SHEET.


FOR PILE CONCRETE RESTORATION, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM DETAILS AND UNDERWATER MORTAR REPAIRS, SEE ``PILE FRP PROTECTIVE SYSTEM DETAILS'' SHEET.



- FRP PROTECTIVE SYSTEM
- SHOTCRETE REPAIRS
- PILE FOOTING RESTORATION \times



▲ FRP PROTECTIVE SYSTEM BELOW WATERLINE MAY INCLUDE APPROVED UNDERWATER MORTAR REPAIRS

APPROX. NORMAL WATER	PROJECT NO. <u>HB-0017</u> <u>DARE</u> county BRIDGE NO. <u>270009</u>			
8 SILING TH CAROLINI	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH			
8 V L.3 SEAL SEAL O20208 NG/NEF B. NELSON NUM DocuSigned by: Eir Bhul G 7/14/2022 ACB8082119D74CD	BENT 140 West face			
enue	REVISIONS SHEET NO.			
DOCUMENT NOT CONSIDERED	NO. BY: DATE: NO. BY: DATE: S-217			
FINAL UNLESS ALL SIGNATURES COMPLETED	1 3 TOTAL SHEETS 2 4 355			