

+

+

	AS-BUILT REPA	JANTI	ITY TABLE					
	BENT 144							
	CAP REPAIRS	ESTIMATE		ACTUAL				
	SHOTCRETE REPAIRS	- SF	- CF	SF	CF			
	EPOXY RESIN INJECTION	- LF ESTIMATE			LF			
	COLUMN REPAIRS			ACTUAL				
	SHOTCRETE REPAIRS	57.9 SF	29.0 CF	SF	CF			
	EPOXY RESIN INJECTION	- LF ESTIMATE - SF		LF				
	PILE REPAIRS			ACTUAL				
	FRP PROTECTIVE SYSTEM AWL			SF				
	FRP PROTECTIVE SYSTEM BWL	363.) SF	SF				
FOR CAP REPAIRS: VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS								

FOR CAP REPAIRS: VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR DETAILS, SEE ``TYPICAL CAP, COLUMN & UNDERDECK REPAIR DETAILS''& ``PILE CONCRETE RESTORATION DETAILS'' SHEETS.

FOR FOOTING,COLUMN,AND STRUT REPAIR DETAILS,SEE ``PILE FOOTING RESTORATION''SHEET.

FOR PILE CONCRETE RESTORATION, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM DETAILS AND UNDERWATER MORTAR REPAIRS, SEE ``PILE FRP PROTECTIVE SYSTEM DETAILS' SHEET.

ERI - EPOXY RESIN INJECTION

- FRP PROTECTIVE SYSTEM
- SHOTCRETE REPAIRS
- PILE FOOTING RESTORATION

▲ FRP PROTECTIVE SYSTEM BELOW WATERLINE MAY INCLUDE APPROVED UNDERWATER MORTAR REPAIRS

	PROJECT	FNO.	HE	3-001	7
		DAR		CC	UNTY
OX. Al R Ace	BRIDGE	NO	27	70009)
DEPARTMENT OF TRANSPORTAT					
DocuSigned by: Exi BML A 7/14/2022 ACB8082119D74CD	BENT 144 West face				
e	REVISIONS				SHEET NO.
DOCUMENT NOT CONSIDERED FINAL UNLESS ALL	NO. ВҮ:	DATE:	NO. BY:	DATE:	S-225 Total sheets
SIGNATURES COMPLETED	2		A		355