

+

+

AS-BUILT REPA	AIR QU	JANTI	TY TA	BLE					
BENT 155									
CAP REPAIRS									
SHOTCRETE REPAIRS	5.0 SF	2.5 CF	SF	CF					
EPOXY RESIN INJECTION	_	LF		LF					
PILE REPAIRS									
PILE CONCRETE RESTORATION	60.8 SF	25.3 CF	SF	CF					
FRP PROTECTIVE SYSTEM AWL	213.	5 SF							
FRP PROTECTIVE SYSTEM BWL	73.2	2 SF							
BENT 156									
CAP REPAIRS									
SHOTCRETE REPAIRS	2.2 SF	1.1 CF	SF	CF					
EPOXY RESIN INJECTION	_	LF		LF					
PILE REPAIRS									
PILE CONCRETE RESTORATION	10.0 SF	3.8 CF	SF	CF					
FRP PROTECTIVE SYSTEM AWL	48.8	3 SF							
FRP PROTECTIVE SYSTEM BWL	18.3	SF							
FOR CAR DERATRS VALUES THE CU									

FOR CAP REPAIRS: VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2" CL. TO SAWCUT. SEE REPAIR DETAILS. NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR DETAILS, SEE ``TYPICAL CAP, COLUMN & UNDERDECK REPAIR DETAILS'' & ``PILE CONCRETE RESTORATION DETAILS'' SHEETS. FOR PILE CONCRETE RESTORATION, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM DETAILS AND UNDERWATER MORTAR REPAIRS, SEE ``PILE FRP PROTECTIVE SYSTEM DETAILS'' SHEET.

	ESTIMATED PILE CRACK QTY. TABLE									
E			NW	W	SW	S	SE	E	NE	Ν
NE SE B		PILE 1	2	_	7	5	3	_	6	6
	BENT	PILE 2	_	_	7	_	2	6	3	_
	155	PILE 3	6	-	5	-	7	6	_	3
NW SW		PILE 4	-	_	7	-	6	3	_	_
W		PILE 1	-	6	3	_	-	7	6	3
TEM BELOW UDE	BENT	PILE 2	_	_	_	_	_	_	_	_
r mortar	156	PILE 3	_	_	_	_	_	-	-	_
		PILE 4	_	_	_	_	_	_	_	_
NOTE: FOR INFORMATION ON PILE CONDITION ONLY.										
PROJECT NO. <u>HB-0017</u>										
N INJECTION	I	NOOLO							<u> </u>	
TIVE SYSTEMDARECOUNTY							ΛΤΥ			
TE RESTORATION BRIDGE NO. 270009										
REPAIRS	1									
	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH									
DocuSigned by:										
Ie				REVIS	SIONS				SH	EET NO.
DOCUMENT NOT	CONSIDERED	NO. BY:	DAT	E:		BY:	D.	ATE:		5-247
FINAL UNLE SIGNATURES C		1			3 4				_	total sheets 355
										000