

+

+

AS-BUILT REPA	IR QUANTITY TABLE								
BENT 209									
CAP REPAIRS									
SHOTCRETE REPAIRS	3.1 SF	1.6 CF	SF	CF					
EPOXY RESIN INJECTION	_	LF		LF					
PILE REPAIRS									
PILE CONCRETE RESTORATION	74.9 SF	31.8 CF	SF	CF					
FRP PROTECTIVE SYSTEM AWL	289.	8 SF							
FRP PROTECTIVE SYSTEM BWL	73.2	2 SF							
BENT 210									
CAP REPAIRS									
SHOTCRETE REPAIRS	1.5 SF	0.8 CF	SF	CF					
EPOXY RESIN INJECTION	_	LF		LF					
PILE REPAIRS									
PILE CONCRETE RESTORATION	7.5 SF	3.2 CF	SF	CF					
FRP PROTECTIVE SYSTEM AWL	139.3	3 SF							
FRP PROTECTIVE SYSTEM BWL	36.6	S SF							

FOR CAP REPAIRS: VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2" CL. TO SAWCUT. SEE REPAIR DETAILS. NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR DETAILS, SEE ``TYPICAL CAP, COLUMN & UNDERDECK REPAIR DETAILS'' & ``PILE CONCRETE RESTORATION DETAILS'' SHEETS. FOR PILE CONCRETE RESTORATION, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM DETAILS AND UNDERWATER MORTAR REPAIRS, SEE ``PILE FRP PROTECTIVE SYSTEM DETAILS'' SHEET.

E	ESTIM	ATED F	TLE		RAC	K (	)ΤΥ	. T <i>i</i>	ABL	E
NE/ SE			NW	W	SW	S	SE	E	NE	Ν
		PILE 1	8	_	-	_	_	_	9	3
N L J S	BENT	PILE 2	8	3	3	5	12	_	-	10
NW	w sw 209	PILE 3	-	-	4	_	_	7	7	-
W		PILE 4	-	-	-	5	5	4	8	7
	BENT 210	PILE 1	_	_	_	_	_	_	_	_
TEM BELOW Ude		PILE 2	-	-	-	_	_	_	-	_
R MORTAR		PILE 3	6	9	-	-	7	7	-	_
		PILE 4	4	_	-	_	6	4	9	12
	NOTE:FOR IN	IFORMATIO	N ON	PIL	E CO	NDIT	ION	ONL`	Ý.	
PROJECT NO. <u>HB-0017</u>										
N INJECTION	ľ		_	. —				_	<u> </u>	
TIVE SYSTEMDARECOUI						OUN	I I Y			
ETE RESTORATION BRIDGE NO. 270009										
REPAIRS	]									
	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH									
DocuSigned by: Etic B That ACB8082119D74C	J 7/14/2022	BEN	Ţ	209	9 8	2	BE	NT	2	210
le		REVISIONS SHEET								EET NO.
DOCUMENT NOT		NO. BY:	DAT	E:	NO.	BY:	D	ATE:		5-274 Totai
FINAL UNLE SIGNATURES C		1 2			3 4				-	total sheets 355