

+

+

AS-BUILT REPA	AIR QU	JANTI	τγ τα	TABLE					
BENT 235									
CAP REPAIRS									
SHOTCRETE REPAIRS	- SF	- CF	SF	CF					
EPOXY RESIN INJECTION	_	LF		LF					
PILE REPAIRS									
PILE CONCRETE RESTORATION	23.8 SF	10.1 CF	SF	CF					
FRP PROTECTIVE SYSTEM AWL	258.	5 SF							
FRP PROTECTIVE SYSTEM BWL	99.() SF							
BENT 236									
CAP REPAIRS									
SHOTCRETE REPAIRS	24.1 SF	12.1 CF	SF	CF					
EPOXY RESIN INJECTION	- LF			LF					
PILE REPAIRS									
PILE CONCRETE RESTORATION	49.4 SF	20.4 CF	SF	CF					
FRP PROTECTIVE SYSTEM AWL	203.	5 SF							
FRP PROTECTIVE SYSTEM BWL	66.() SF							

FOR CAP REPAIRS: VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2" CL. TO SAWCUT. SEE REPAIR DETAILS. NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR DETAILS, SEE ``TYPICAL CAP, COLUMN & UNDERDECK REPAIR DETAILS'' & ``PILE CONCRETE RESTORATION DETAILS'' SHEETS. FOR PILE CONCRETE RESTORATION, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM DETAILS AND UNDERWATER MORTAR REPAIRS, SEE ``PILE FRP PROTECTIVE SYSTEM DETAILS'' SHEET.

E	ESTIM	ATED P	ILE	C F	RAC	K (Υ ΤΩ	. T/	ABL	E
NE/			NW	W	SW	S	SE	E	NE	Ν
N S S S S S S S S S S S S S S S S S S S		PILE 1	_	_	6	_	7	_	4	4
		PILE 2	-	7	-	-	_	_	5	_
	BENT 235	PILE 3	5	7	-	_	8	_	-	_
		PILE 4	_	7	8	-	6	8	-	8
		PILE 5	4	_	4	_	4	_	-	_
		PILE 6	4	_	_	6	_	3	3	6
		PILE 1	-	_	_	_	_	_	-	6
TEM BELOW Ude	BENT	PILE 2	-	_	6	8	_	_	7	_
R MORTAR	236	PILE 3	-	8	6	3	4	_	3	_
		PILE 4	-	4	4	_	7	_	-	4
	NOTE:FOR IN	IFORMATIO	N ON	PIL	e co	NDIT	ION	ONL`	Ý.	
		PROJEC	ΤN			⊣[$\exists -($	$\left(\right) \left(\right)$	17	
N INJECTION			_	. —						
TIVE SYSTEM		DARECOUNTY								
ETE RESTORATION BR		BRIDGE NO. 270009								
				•••						
REPAIRS										
SEAL 020208		STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH								
DocuSigned by:	SEAL 20208 VGINEER B. NELSONIUM	BEN ⁻	Γ 2	235	5 8	X	BE	NT	2	36
ACB8082119D74C	D	REVISIONS SHEET NO.								
	NO. BY:	DAT		NO.	BY:	D	ATE:		6-287	
DOCUMENT NOT FINAL UNLE	ESS ALL	1			3					TOTAL SHEETS
SIGNATURES C	COMPLETED	2			4					355